



The South Park Bridge Story



Corrosion under the deck grating



Cracks in the pier wall



Deteriorating concrete in piers



Concrete is crumbling away from outer surface at water line



Damage to railing due 2001 Nisqually earthquake



Exposed re-bar on main pier



Repairs to the teeth at center of span



Cracked Concrete Supports



Rotted timber protection pier